

Шаг резьбы для основной и мелкой резьбы

Резьба	Шаг резьбы P, мм			
	Основная резьба M	Мелкая резьба M		
		Мелкая	Мелкая 2	Супер мелкая
M1	0.25	(0.2)	-	-
M1.2	0.25	(0.2)	-	-
M1.4	0.3	(0.2)	-	-
M1.6	0.35	(0.2)	-	-
M1.8	0.35	(0.2)	-	-
M4	0.7	0.5	-	-
M5	0.8	0.5	-	-
M6	1	0.75	0.5	-
M8	1.25	1	0.75	0.5
M10	1.5	1.25	1	0.75
M12	1.75	1.5	1.25	1
M14	2	1.5	1.25	1
M16	2	1.5	-	1
M18	2.5	2	1.25	1
M20	2.5	2	1.25	1
M22	2.5	2	1.5	1
M24	3	2	1.5	1
M27	3	2	1.5	(1)
M30	3.5	2	1.5	(1)
M33	3.5	2	1.5	-
M22	2.5	2	1.5	1
M24	3	2	1.5	1
M27	3	2	1.5	(1)
M30	3.5	2	1.5	(1)
M33	3.5	2	1.5	-
M36	4	3	2	1.5
M39	4	3(4)	2	1.5
M42	4.5	3(4)	2	1.5
M45	4.5	3(4)	2	1.5
M48	5	3	2	1.5
M52	5	(4)3	2	1.5
M56	5.5	4	3(2)	1.5
M60	5.5	4	3(2)	1.5
M64	6	4	3	2(1.5)
M68	6	4	3	2(1.5)